


INSTALLATION OF CART & TRACK



1. Place (2) long rails on Abrasive Recovery System. Each rail has a drilled hole in end toward extended track.
2. Place cart on rails. Adjust position of rails so sandblast nozzle will be about correct distance from monument setting on cart.
3. Move middle support and end support into position.
4. Lay (2) short rails on supports. Loosely connect short rails to long rails with 3/8" bolts, nuts, & lockwashers. Loosely bolt rails to middle and end supports. Once all connections are made, fully tighten all bolts.
5. Mount stop blocks on track in booth.
6. Check each leg for contact with floor. If not in contact, extend threaded leveling bolt at bottom of leg.