

Electric Quick Shutoff Valve Installation Instructions

Feb. 9, 2016

1. Position box on right hand oil tank and clamp in place as shown below.



2. Run the black and yellow air lines from the Empire Blast Pot as shown below.



3. Connect the black and yellow air lines to the labeled ports.
Use small hose clamps so they do not blow off.



4. Plug it in.